## PRODUCT SERVICE BULLETIN (REVISED)

Issue date: 5 September 2010

Page 1 of 1

Bulletin number: SB AMMO050910/2 -This Service Bulletin replaces SB AMMO050910/1-

**Subject:** Mandatory cutter replacement

**Identification:** Argus Cutter with manufacturing date Aug. 07 or earlier and manufactured

for the Argus AAD by Nobel Energetics

## Background:

This service bulletin has been issued in response to a notice of the International Parachute Commission. The notice was re-published by the BPA, the USPA and taken into account by the APF. This notice continuous to create confusion and uncertainty.


It was a follow up of a fatality that occurred in Poland on 25 of July 2009. The Polish Authorities concluded in a preliminary report that the loop was only fully cut at impact. We formally disagree with these conclusions.

This service bulletin is published to make an end to this impasse and to err on the side of caution.

## Service bulletin:

Systems that have a cutter of the manufacturing date August 07 or earlier must have the cutter replaced with a later model at the next repack but no later than 31 December 2010. Cutters manufactured as of September '07 use a different, hardened steel blade delivering a clean cut by loops with lesser tension.

The cutter's manufacturing date can be identified by the cable tag:



Any senior or master rigger can unscrew the cutter and replace the old cutter with the approved one. The connector must be locked hand tight in order to ensure water resistance.

Compliance date: At the next repack but no later than 31 December 2010. The cutter will be

replaced free of charge.

Aviacom SA

Authority: Karel Goorts, Managing director

Avenue Lavoisier 18 B-1300 Wavre, Belgium Phone: +32-(0)485 868 788

## The distribution list shall include but is not limited to:

- All dealers and owners/customers for whom addresses are on file.
- PIA Technical Committee
- IPC Technical Committee
- · All parachuting periodicals
- National Aero Clubs-Parachuting sections