

April 6, 2011

## **Argus Service Bulletins**

### **+ Users- & Installation Manuals**

#### **Argus Multi-mode AAD**

<mailto:karel@argus-aad.com>

Dear Skydiver,

Please accept our apologies for all the trouble that the recent grounding caused you. This was out of our control.

In order to get your Argus back in the air ASAP and for your safety, we've issued this service bulletin:

[http://tools.emailgarage.com/Pub/d\\_DqHQAAAA~ar2kmW1TT0G8rwKS-MY5xQ~/Html/GotoLink.ashx](http://tools.emailgarage.com/Pub/d_DqHQAAAA~ar2kmW1TT0G8rwKS-MY5xQ~/Html/GotoLink.ashx) <[http://tools.emailgarage.com/Pub/d\\_DqHQAAAA~/LHDpHgJtUkOXPRPd7fkV\\_Q~/Html/GotoLink.ashx](http://tools.emailgarage.com/Pub/d_DqHQAAAA~/LHDpHgJtUkOXPRPd7fkV_Q~/Html/GotoLink.ashx)> **Cutter replacement**

Based on our testing and analysis, there is no longer a need to replace cutters placed below the pilot chute, so the mandatory cutter replacement is no longer required, and the previous bulletin does not apply for those configurations.

**You will also find our new Argus installation guide**

<[http://tools.emailgarage.com/Pub/d\\_DqHQAAAA~/LfFrRusyc0Cd0nSFvy9UsQ~/Html/GotoLink.ashx](http://tools.emailgarage.com/Pub/d_DqHQAAAA~/LfFrRusyc0Cd0nSFvy9UsQ~/Html/GotoLink.ashx)> for the riggers

What's new: Warning for loops length. See page 27.

**And the new Argus Users' Manual**

<[http://tools.emailgarage.com/Pub/d\\_DqHQAAAA~/IZjVMIHDXkqXtspITc5COQ~/Html/GotoLink.ashx](http://tools.emailgarage.com/Pub/d_DqHQAAAA~/IZjVMIHDXkqXtspITc5COQ~/Html/GotoLink.ashx)> is now available. We noticed that a lot of skydivers did not replace the batteries after the mandatory 12 months.

We now require the replacement of the batteries each pack cycle or after cutter activation.

Kind regards,

Karel Goorts  
Aviacom Sa  
Phone +32 2 785 02 80