

**AAD sa/nv**  
Bld A.Reyers, 193  
1030 Brussels – Belgium – Europe  
+32 2 732 65 52 – Fax : +32 2 736 06 27  
[www.vigil.aero](http://www.vigil.aero) - [info@vigil.aero](mailto:info@vigil.aero)

## **PRODUCT SERVICE BULLETIN**

**Issue Date** : **June 14, 2013**

**Bulletin Number** : **PSB-9**

**Subject** : **Waterproof Inspection of Vigil II Multimode  
(Civilian model only; does not apply to Military model)**

**Compliance** : **Mandatory**

### **Identification:**

All Vigil AAD II multimode (Civilian model) S/N 8021 or higher  
Date of Manufacture: 05-07 (**mm-yy**) or later

### **Background:**

Upon checking returned Vigil II Multimode (Civilian model) units after water immersions, A.A.D. nv/sa discovered, in some cases, high humidity inside the main box unit.

In one instance, the Vigil could not be switched on again after a water landing/water immersion. In another instance, the Vigil continued working for several jumps after a water landing/water immersion and then could not be switched on.

To avoid potential problems with the electronics in Vigil II Multimode (Civilian model) units after contact with water, and possible malfunction of the unit, A.A.D. nv/sa must inspect each Vigil II Multimode (Civilian model) unit, after it has been in contact with, or immersed in, fresh or salt water, before the next jump.

### **Compliance:**

**If a Vigil II Multimode (Civilian model) has been in contact with, or immersed in, fresh or salt water, it is mandatory to return the Vigil to A.A.D. nv/sa for an inspection of the unit, before the next jump.** Contact A.A.D. nv/sa or Vigil America, Inc. for instructions on how to return the unit.

**Authority:**

Jo Smolders  
Managing Director

Edwin Bollaerts  
Office Manager

**AAD sa/nv**

Bld A.Reyers, 193  
1030 Brussels – Belgium – Europe  
+32 2 732 65 52 – Fax : +32 2 736 06 27  
[www.vigil.aero](http://www.vigil.aero) - [info@vigil.aero](mailto:info@vigil.aero)

**Vigil America, inc.**

1400 Flightline Blvd suite C  
Deland, FL 32724  
+386 736 8464 – Fax : +386 736 8468  
[www.vigil.aero](http://www.vigil.aero) - [candace@vigil.aero](mailto:candace@vigil.aero)

**Distribution of this Advisory Product Service Bulletin shall include, but is not limited to:**

- All identified owners of Vigil II Multimode SN 8021 or later.
- All AAD dealers.
- Parachute Industry Association.
- All identified parachuting publications.
- All identified parachuting Federations and Associations
- All National Aero Clubs, Parachuting Section.
- IPC Technical Committee.